

Educational

Mayfield Primary School, Cambridge

The main teaching areas of Mayfield School were destroyed by fire. Temporary classrooms were placed on site whilst the major part of the school was rebuilt. Peter Dann were involved with an internal inspection immediately after the fire and then as part of the professional team re-building the classrooms.

Working directly for Cambridge County Council Property Management Services, we carried out a ground investigation and designed the foundations to all the new structures and the superstructure to the hall, gym, community room and tank room. The classrooms were system build structures design and erected by others.

The new community hall was separate from the classrooms and in filled a courtyard area. The square pyramid roof has feature working and dummy trusses and has a continuous band of high level glazing. We also surveyed the existing drainage and designed the new drainage.

The project was handed to the school in stages allowing optimum use of the new facilities.

